Release Note for VigorAP 800

Firmware Version: 1.0.1
Built Date: November 23, 2010
Applied Models: VigorAP 800

With this high cost-efficiency VigorAP 800, computers and wireless devices which are compatible with 802.11n can connect to existing wired Ethernet network via this VigorAP 800, at the speed of 300Mbps. Easy install procedures allows any computer users to setup a network environment in very short time - within minutes, even inexperienced users. Just follow the instructions given in this user manual, you can complete the setup procedure and release the power of this access point all by yourself!

New Features

- Support internal RADIUS server. (For 2.4G/5G wireless could be used as stand-alone RADIUS server.)
- Support 5G wireless LAN.
- Support TR-069 for LAN-A. Basic function: Firmware upgrade, Configuration backup/restore.

Improvement

- Fixed: Wireless rate doesn't match with wireless mode.
- Fixed: Wireless PHY mode field is gray and cannot be set.
- Fixed: Cannot set 192.168.2.0/24 network for LAN-A.
- Fixed: LAN-B DHCP Server doesn't work properly while LAN_A DHCP server is factory default value.

Related Information

- Get the document, please visit http://www.draytek.com/user/PdInfoDetail.php?Id=122
- Get the new firmware, please visit http://www.draytek.com/user/SupportDownloads.php
- Get the customer service support, please visit http://www.draytek.com.tw/user/ContactHeadquarters.php
- Get the regulatory compliance http://www.draytek.com.tw/user/AboutRegulatory.

| information | php |
| Get information for global partners | http://www.draytek.com.tw/user/Globalpartners.php |

Known Issue

- None

Notes

Modifications

- None

Bug Lists

- None